

MUNICIPAL COUNCIL OF KIRANDUL

DISTRICT SOUTH BASTAR DANTEWADA (C.G.)

PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

CERTIFICATE

No. 703

Dated: 14/08/2026

It is certified that an inspection team headed by Shri Shashi Bhushan Mahapatra
Chief Municipal officer (Name of Officers with designation) from Municipal
Council Kirandul (Name of Officers with designation) from Civil Dept.
Municipal council Kirandul (Name of Department/Office inspected the DAV
PUBIC SCHOOL KIRANDUL-494556 (Name & Address of the School) On
14-08-26 (date of inspection) and found that the DAV PUBLIC SCHOOL,
KIRANDUL (Name of School) has safe drinking water facilities for the
students and members of staff of the institution and is maintaining the
hygienic sanitation condition in the school building & the campus as per the
norms prescribed by the Central/State/U.T. Govt.

The above valid for a period of One Year.


CHIEF MUNICIPAL OFFICER
Municipal Council Kirandul
Distt. South Bastar Dantewada (C.G.)

Signature with seal

Name: Shashi Bhushan Mahapatra

Designation Chief Municipal officer

Name & Address of Department/office Kirandul

To,

Principal

DAV Public School, Kirandul

(Name o& Address of the Institution)

* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificates as a single pdf.